Work Ordo May 3, 2010 11	1.7	303							•		Page
Item ID: Revision ID:	D3915-1	£ _ +		Accept				 s	Setup Star	t	
Item Name:	Rib								Stop		
Start Date: Required Date: Reference:	03/05/2010 13/05/2010	Start Qty: 6.00 Req'd Qty: 6.00			Cust Item I Customer:	D:				Towns.	
Approvals:	Process Pla	an:	Date:/05-03	Tooling: SPC (Y/N):		ate:		F	Run Star Stop		
Sequence ID/ Work Center II	D	Operation Description	~ .	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	vision Nbr					-				
D3915.	В										
Large Fab		2- Drill h	pe as per dwg D1019 nole as per dwg 179618 e identification marks and debu	0.00 0.00 SA	10 5-05-0	4		6			
QC Quality Control		QC5- Inspect part con	npleteness to step on W/O	0.00 Calos	04			(To)		
120 Packaging		Identify as per dwg & Memo	Stock Location: WA	0.00 SA	05.04		1	6			

Packaging

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: \	es N	o DQA		_ Date: _	
	R	esolution:	Disposition: QA: N/C Closed:				Date:			
NCR:		\	WORK ORD	ER NON-CONFORM	ANCE (N	ICR)				
DATE	STEP	Description of NC	Corrective Action Section B			Verific		ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Section	ı C	Chief Eng	QC Inspector
									·	
				-						
						, , , =				
										<u> </u>

Work Order ID 58303

May 3, 2010 11:18:52 AM



Page 2

Item ID:

D3915-1

Accept



Setup Start

Stop



Revision ID:

Item Name: Rib

03/05/2010 **Start Date: Required Date:** 13/05/2010 Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID: Customer:

Reference:

А	nn	ro	va	Is:	

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:_____

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID

130

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**

0.00

Draw Number

Draw Rev.

Plan Accept Code Qty

Reject Reject Qty

Insp. Number Stamp

Memo

0.00

Dart Ae									÷
W/O:			` W	ORK ORDER CHANGE	S	***************************************			
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
Part No				egory:			ł .		
	Heso	lution:	Disposition	on:	QA: N/C Cld	sed:		Date:	
NCR:	i		140014000						
			WORK ORD	ER NON-CONFORMAN					
DATE	CTED			Corrective Action Section	NCE (NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng		NCE (NCR		ation	Approval Chief Eng	Approva
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	B Sign &) Verific	ation	Approval	Approva
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	B Sign &) Verific	ation	Approval	Approva
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	B Sign &) Verific	ation	Approval	Approva QC Inspect
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	B Sign &) Verific	ation	Approval	Approva
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	B Sign & Date) Verific	ation	Approval	Approva

Picklist Print

May 3, 2010 11:18:57 AM

Work Order ID: 58303

Parent Item: D3915-1

Rib Parent Item Name:

IPP Rev:A new issue DD 10.03.19 verified by:EC

per dwg revB DD 10.04.20 verified by:EC

IPP Rev:B as

Start Date: 03/05/2010

Required Date: 13/05/2010

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/

Comments:

Item Name

M6061T6TS0.750W.06

Replacement Mfg/ Item ID Purch Purchased Bin Item No

Primary Location Last Location Route Seq ID 100

Unit of

Qty on Measure Hand 77.6752

Qty per Kit Qty Issued 8

Date Issued Status

Page 1

6061-T6 SQ Tube .75 x .75 x .062W

Location	i	Loc Oty	Loc Code
MAT06		77.6752	
	103069	38.0526	
	104422	15.5263	
	16441	4.07	
	9671	20.0263	

M(14573

\$ 50.5263 (8 picca)

M6061T6TS0.750W.062 M114573

Dart Aerospace	Ltd
----------------	-----

	•									¥
W/O:			WC	RK ORDER CHAN	GES					•
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	C	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•						
Part No	:	PAR #:	Fault Cate	gory:	NCR: Y	es No	DQA	:	_ Date: _	
	R	esolution:	Disposition	n:	QA: N/C	Close	ed:		Date:	
NCR:		V	WORK ORDI	ER NON-CONFORM	MANCE (N	CR)				
DATE	STEP	Description of NC	Corrective Action Section B			Sign & Verific			Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng		ate	Sectio	n C	Chief Eng	QC Inspector
									,	
								!		
										i
	:							:		
							1			

1796/8

DART AEROSPACE LTD	Work Order:	58303
Description: Rib	Part Number:	3915-1
Inspection Dwg: 139/5 Rev: B		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.38	<u>た 0.030"</u>	.375"			Vern. Tape	
6.31	//	6.30			Tape	
6.00	"	6.වე			'''	
29.11	"	29.11			"	
7.00	"	7.00			"	
52.89	И	52.90			4	
77.69	"	77.70			u	
\$0.125	+.004 /001	0.128			VerN.	
	/	'				
			$\overline{}$			

Measured by:	M	Audited by:	8	Preliminary Approval:	ls	1
Date:	10.05.04	Date:	(0/05/04	Date:		4


Rev	Date	Change	Revised by	Approved
E	10.04.14	Added preliminary approval	KJ	

\$ 10.00e.15




Dart A	\ero	spac	e L	.td
--------	------	------	-----	-----

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,	****						
Part No:		PAR #:	Fault Category: NCR: Yes No DQA			A: Date:			
	R	esolution:	Disposition: QA: N/C Closed:				Date:		
NCR:			WORK ORD	DER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	Initial		tion B	Verific	ation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Sign Date		n C	Chief Eng	QC Inspector
									}
									}
									:
									<u> </u> -




Dart	Aerospace	Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PRO	CEDURE CH	ANGE	•	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:								
			WORK ORDER NON-CONFORMANCE (NCR)				Date:			
NCR:	1	V	VORK ORL	JER NON-CONFORM	ANCE (NCH)				
DATE	STEP	Description of NC Section A	Corrective Action Section		Section B on Sign & Date		Verific Section			Approval QC Inspector
										W-7
		-								
				V1 M22 - 19440						
										•



Dart	Aeros	pace	Ltd
------	--------------	------	-----

	•							1		and S	
W/O:		·	WORK ORDER CHANGES							*****	
DATE	STEP	PRO	CEDURE CH	IANGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
										·	
				Ļ							
· · · · · · · · · · · · · · · · · · ·											
Part No	:	PAR #:	Fault Ca	tegory:	NCR:	Yes N	lo DQA	\.	Date:		
			Disposition: QA:			A: N/C Closed:			Date:		
NCR:		V	WORK OR	DER NON-CONFORM	MANCE (VCR)					
DATE	STEP	Description of NC		Corrective Action Section B			Verification		Approval	Approval	
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section		Chief Eng	QC Inspector	
				· ·							
	-										
						•					



!

Dart Aerospa	ace Ltd
--------------	---------

W/O:			V	ORK ORDER C	HANGE	S					
DATE	STEP	PRC	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									F100 Mgi		
			184 184								
		· -	·	•							
	:	×.,									
						-					
Part No	:	PAR #:	Fault Ca	tegory:		NCR: Yes	No DQ	A: Date:			
	Resolution: Disposition: QA: N/C Closed:										
NCR:			WORK OR	DER NON-CONF	ORMAN	ICE (NCR)				
DATE	CTED	Description of NC Corrective Action Section			Section		ation	Approval	Approval		
	STEP	Section A	Initial Chief Eng	Action Desc Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector	
				ā.					·		
									,		
		,							<u>'</u>		
			,								
			·								
										45.	
					•						